



Product Safety Recall

PSRS 2025-01

Recall Details

Recall Date	2025-04-04
Last Updated	2025-04-04
Notification Type	Safety Mfr
System	Accelerator Pedal Assembly
Issued by	ARGO
Manufacturer Recall Number	PSRS 2025-01
Units Affected	185 (USA and Canada)
Category	SSV

Recall Details

Issue:

On certain SSVs, a faulty accelerator pedal assembly may contact an interior panel.

Safety Risk:

A faulty accelerator pedal assembly may contact an interior panel which may pose an operation risk of a crash resulting in serious injury. No reports of personal injury have been identified.

Corrective Actions:

Immediately STOP using the affected model(s) until your vehicle's accelerator pedal has been replaced. Contact your original selling dealer to schedule a free accelerator pedal replacement or visit www.argotv.com and use the Dealer Locator to locate your nearest authorized ARGO ATV/Side-by-Side dealer. DO NOT attempt to make any repairs yourself.

Make	Model	Model Year(s) Affected
ARGO	MAGNUM XF 1000 LE	2025 VIN# 000443 - 000711

Manufacturer Name	Contact Info	Web Site
ARGO	www.argotv.com/contact	www.argotv.com/recalls



2025 Magnum
XF 1000 LE